

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
08/19/2015

Document Number:
679900231

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>258179</u>	<u>304321</u>	<u>Welsh, Brian</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>10112</u>
Name of Operator:	<u>FOUNDATION ENERGY MANAGEMENT LLC</u>
Address:	<u>16000 DALLAS PARKWAY #875</u>
City:	<u>DALLAS</u> State: <u>TX</u> Zip: <u>75248-</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Grant, Rachael	918-585-1650 ext 212	rgrant@foundationenergy.com	

Compliance Summary:

QtrQtr: NWSW Sec: 5 Twp: 2S Range: 43W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
09/16/2014	668900174	PR	PR	ACTION REQUIRED	P		No
01/30/2013	668600291	PR	PR	SATISFACTORY	P		No
11/01/2010	200283756	PR	PR	SATISFACTORY			No
07/02/2007	200114180	PR	PR	SATISFACTORY		Pass	No
12/22/2000	200013659	DG	DG	SATISFACTORY	P	Pass	No

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
258179	WELL	PR	10/01/2008	GW	125-08243	MCCLUNG 13-5	PR	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:				
Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY	DIRT ROAD THROUGH PASTURE		

Signs/Marker:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
OTHER	ACTION REQUIRED	LEASE SIGN AT METER SHED FOR MCCLUNG 13-5. NO SIGN FOR ASSOICATED WELLS	Install sign to comply with rule 210.	09/16/2014
WELLHEAD	SATISFACTORY	LEASE SIGN BY UNIT		
TANK LABELS/PLACARDS	SATISFACTORY	METAL SIGN BY WATER TANK		

Emergency Contact Number (S/A/V): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
OTHER	SATISFACTORY	METAL PANELS AROUND METER SHED AND VGS		
PUMP JACK	SATISFACTORY	METAL PANELS AROUND UNIT AND WATER TANK		

Equipment:					
Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Prime Mover	1	SATISFACTORY	KOHLER GAS ENGINE		
Gas Meter Run		SATISFACTORY	SHARED METER RUN FOR (MCCLUNG 13-5, ALLISON 44-6, 41-6X AND 33-6) 900' NW OF WELLHEAD		
Deadman # & Marked	4	SATISFACTORY			
Vertical Separator		SATISFACTORY	4-VERTICAL GAS SEPARATORS 50% BURIED BY METER SHED		
Ancillary equipment	2	SATISFACTORY	TELEMETRY EQUIPMENT AND GAS SCRUBBER		

Inspector Name: Welsh, Brian

Pump Jack	1	SATISFACTORY	JENSEN UNIT		
-----------	---	--------------	-------------	--	--

Facilities: New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS	39.910510,-102.220410

S/A/V: SATISFACTORY Comment: **FIBERGLASS WATER TANK 50% BURIED**

Corrective Action: _____ Corrective Date: _____

Paint

Condition: _____

Other (Content) _____

Other (Capacity) 150BBL _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action _____ Corrective Date _____

Comment: **BERMS AROUND UNIT AND TANK**

Venting:

Yes/No	Comment
NO	

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 258179

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: SATISFACTORY **Comment:** NO COA'S

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 258179 Type: WELL API Number: 125-08243 Status: PR Insp. Status: PR

Producing Well

Comment: PRODUCING. CASING PRODUCTION. CENTRAL METER RUN FOR (ALLISON 44-6, 41-6X, 33-6, MCCLUNG 13-5) 900' NW @ 39.91251/-102.22281

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ **Date:** _____

Inspector Name: Welsh, Brian

Reportable: _____	GPS: Lat _____	Long _____
Proximity to Surface Water: _____	Depth to Ground Water: _____	

Water Well:

DWR Receipt Num: _____	Owner Name: _____	GPS: _____	Lat _____	Long _____
------------------------	-------------------	------------	-----------	------------

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____ CA _____ CA Date _____

Waste Material Onsite? Pass CM _____ CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____ CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____ CA _____ CA Date _____

Guy line anchors removed? _____ CM _____ CA _____ CA Date _____

Guy line anchors marked? Pass CM _____ CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

Inspector Name: Welsh, Brian

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location

Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass					

S/A/V: SATISFACTOR
Y _____

Corrective Date: _____

Comment: **BERMS AROUND TANK AND WELLHEAD FOR STORMWATER BMP**

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679900231	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3665669