



Photo 1. View of northern portion of project area from entrance to well pad facing westward. Musk thistle (*Carduus nutans*) plants that appear treated are present along the edge of the working area.



Photo 2. View from northwestern corner of project area facing center. Grasses such as soft brome (*Bromus inermis*), western wheatgrass (*Pascopyrum smithii*), and crested wheatgrass (*Agropyron cristatum*) are established within the interim reclamation area.



Photo 3. View of southern portion of project area from southwestern corner facing eastward.