



photo 1 : Center of the location facing north.



photo 2: Center of the location facing west.



photo 3: Center of the location facing south.



photo 4: Center of the location facing east.



photo 5: Guy line anchors and markers remain at all four corners of the location.



photo 6: Close up of the guy line anchor which has not been removed.



photo 7: Guy line anchors and sand markers remain at all four corners of the location.



photo 8: Metal debris found at the location.