



Photo 1. View of erosional channel (approximately 2 feet wide and 1.5 feet deep) within southern portion of project area. Erosional channel is flowing toward nearby open water (in background of photo).



Photo 2. View of another erosional channel (approximately 12 inches wide and 10 inches deep) within southern portion of project area. Erosional channel is flowing toward nearby open water (in background of photo).



Photo 3. View of Canada thistle (*Cirsium arvense*) plants in southern portion of project area that need to be physically removed.



Photo 4. View of northern portion of project area from northeastern corner facing westward.