

Black Mountain-Federal A-1

Inspection# 673402371

No operator or emergency contact information on battery sign.



No tank label. (label visible is too weathered to discern)
Weeds and vegetation on berm.



No wellhead sign.



Rill and rut in access road transporting sediment onto location. Hard hat for scale.



Rill in access road.
Evidence of sediment
being transported. Hard
hat for scale.

