



**photo 1:** Main access road traveling northwest towards the location. Road repairs have recently been performed.



**photo 2:** Main access road traveling northwest towards the location. Road repairs have recently been performed.



photo 3: Well sign, Apache Canyon 17-13.



photo 4: Facing west towards well head and the cut into the slope.