



photo 1: Main access road traveling west towards the location. Road shows signs of water pooling and vehicle rutting.



photo 2: Main access road facing west near the location. Erosion channels have developed along the road.



photo 3: The 8 inch water bottle indicates depth of erosion channel in the road way.



photo 4: Facing back towards the east along the main access road.



photo 5: The 8 inch water bottle indicates depth of erosion channel in the road way.



photo 6: Erosion channels along the main access road east adjacent to the location.



photo 7: Facing west towards the location.



photo 8: Well sign, Apache Canyon 14-03.