



Photo 1. View of western edge of project area from southwestern corner facing northward. Perimeter wattle and soil stockpile in place.



Photo 2. View of topsoil stockpile in southeastern corner of the well pad.



Photo 3. View of wattles on eastern edge of project area that need maintenance.



Photo 4. View of location on northern edge of project area where sediment appears to be flowing over wattle and needs maintenance.