

Inspector Name: Sherman, Susan

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

08/25/2015

Document Number:

673711357

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	234542	317021	Sherman, Susan	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 95620Name of Operator: WESTERN OPERATING COMPANYAddress: 518 17TH ST STE 200City: DENVER State: CO Zip: 80202

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Crumely, Tim	(970) 768-5959	tcrumley@centurytel.com	
Stapp, D. Scott	(303) 893-2432	scott@westernoperating.com	
James, Steve	(303) 893-2438	steve@westernoperating.com	President

Compliance Summary:QtrQtr: NENW Sec: 4 Twp: 1S Range: 56W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
07/30/2015	673711096	TA	TA	ACTION REQUIRED			No
04/29/2014	673702828	TA	TA	SATISFACTORY			No
08/16/2013	664001213	TA	TA	SATISFACTORY			No
07/30/2012	663400667	TA	TA	ACTION REQUIRED	P		No
04/27/2011	200308733	RT	TA	SATISFACTORY			No
06/24/2010	200258506	RT	TA	SATISFACTORY			No
08/21/2009	200216964	MI	TA	SATISFACTORY			No
03/26/2008	200129381	RT	TA	SATISFACTORY			No
04/10/2007	200109334	RT	TA	SATISFACTORY		Pass	No
05/09/2006	200090130	RT	TA	SATISFACTORY		Pass	No
08/31/2005	200076019	RT	TA	SATISFACTORY		Pass	No
03/31/2004	200052298	MI	SI	SATISFACTORY		Pass	No
03/17/2003	200036482	RT	SI	SATISFACTORY		Pass	No
07/29/2002	200029171	RT	TA	SATISFACTORY		Pass	No
08/16/2001	200019233	RT	TA	SATISFACTORY		Pass	No
07/19/2000	200008102	RT	TA	ACTION REQUIRED		Fail	Yes
07/17/1997	500158732	ID	TA			Pass	No

Inspector Comment:

Inspector Name: Sherman, Susan

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
234542	WELL	TA	01/01/1999	SI	121-06668	BOBCAT D-SAND UNIT 2	TA	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Inspector Name: Sherman, Susan

Predrill

Location ID: 234542

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/A/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/A/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 234542 Type: WELL API Number: 121-06668 Status: TA Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

S/A/V: _____ CA Date: _____

CA: _____

Comment: Last MIT 4/29/2014.

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Inspector Name: Sherman, Susan

Comment:

Corrective Action:

Date:

Reportable:

GPS: Lat

Long

Proximity to Surface Water:

Depth to Ground Water:

Water Well:

Lat

Long

DWR Receipt Num:

Owner Name:

GPS :

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started:

Date Interim Reclamation Completed:

Land Use:

Comment:

1003a.

Debris removed?

CM

CA

CA Date

Waste Material Onsite?

CM

CA

CA Date

Unused or unneeded equipment onsite?

CM

CA

CA Date

Pit, cellars, rat holes and other bores closed?

CM

CA

CA Date

Guy line anchors removed?

CM

CA

CA Date

Guy line anchors marked?

CM

CA

CA Date

1003b.

Area no longer in use?

Production areas stabilized ?

1003c.

Compacted areas have been cross ripped?

1003d.

Drilling pit closed?

Subsidence over on drill pit?

Cuttings management:

1003e.

Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing?

Production areas have been stabilized?

Segregated soils have been replaced?

RESTORATION AND REVEGETATION

Cropland

Top soil replaced

Recontoured

Perennial forage re-established

Inspector Name: Sherman, Susan

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Corrective action from 7/30/2015 inspection #673711096 completed.	ShermaSe	08/26/2015

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673711360	Western Operating Bobcar D-Sand Unit 2 sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3671781