



Photo 1. View of stormwater erosion along the access road and along the road surface. Erosional channel is approximately 2 to 3 feet wide and 18 inches deep.





Photo 2. Another view of the erosional channel shown in Photo 1, and erosion on access road surface.





Photo 3. View of an erosional channel forming within the northwestern portion of the project area.



Photo 4. View from northwestern corner of well pad facing center.





Photo 5. View of western portion of project area facing center from northwestern corner facing southward. Revegetation is progressing here.