

**FORM INSP**  
Rev 05/11

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:  
08/28/2015

Document Number:  
674701782

Overall Inspection:  
SATISFACTORY

**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	335598	335598	LONGWORTH, MIKE	<input type="checkbox"/>	

**Operator Information:**

OGCC Operator Number:	<u>100185</u>
Name of Operator:	<u>ENCANA OIL &amp; GAS (USA) INC</u>
Address:	<u>370 17TH ST STE 1700</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80202-</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, General	970-285-2665	cogcc.inspections@encana.com	EnCana Inspection email

**Compliance Summary:**

QtrQtr:	<u>NESW</u>	Sec:	<u>4</u>	Twp:	<u>6S</u>	Range:	<u>96W</u>
---------	-------------	------	----------	------	-----------	--------	------------

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
12/22/2014	674700768			<b>ACTION REQUIRED</b>			No
06/19/2014	675100086			SATISFACTORY			No
01/14/2014	663902651			SATISFACTORY	F		No
08/12/2013	663900667			SATISFACTORY	I		No

**Inspector Comment:**

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
284957	WELL	PR	06/05/2006	GW	045-12325	N PARACHUTE MF10C N04 696	PR	<input checked="" type="checkbox"/>
284958	WELL	PR	02/01/2014	GW	045-12324	N PARACHUTE MF11D N04 696	PR	<input checked="" type="checkbox"/>
284959	WELL	PR	06/05/2006	GW	045-12323	N PARACHUTE WF17A N04 696	PR	<input checked="" type="checkbox"/>
284960	WELL	PR	06/05/2006	GW	045-12322	N PARACHUTE MF16C N04 696	PR	<input checked="" type="checkbox"/>
284961	WELL	PR	01/08/2007	GW	045-12321	N PARACHUTE MF09C N04 696	PR	<input checked="" type="checkbox"/>
284962	WELL	PR	06/05/2006	GW	045-12320	N PARACHUTE MF16A N04 696	PR	<input checked="" type="checkbox"/>
284963	WELL	PR	01/01/2010	GW	045-12319	N. PARACHUTE MF12D N04 696	PR	<input checked="" type="checkbox"/>
284964	WELL	PR	06/05/2006	GW	045-12318	N PARACHUTE MF09A N04 696	PR	<input checked="" type="checkbox"/>

284965	WELL	PR	01/01/2010	GW	045-12317	N.PARACHUTE MF 18C N04 696	PR	<input checked="" type="checkbox"/>
284966	WELL	PR	06/05/2006	GW	045-12316	N PARACHUTE MF15C N04 696	PR	<input checked="" type="checkbox"/>
284967	WELL	PR	06/05/2006	GW	045-12315	N PARACHUTE MF17C N04 696	PR	<input checked="" type="checkbox"/>
284968	WELL	PR	06/05/2006	GW	045-12314	N PARACHUTE MF18A N04 696	PR	<input checked="" type="checkbox"/>
300233	WELL	PR	12/05/2009	GW	045-17863	N. PARACHUTE MF10A-4 N04 696	PR	<input checked="" type="checkbox"/>
300234	WELL	PR	01/14/2010	GW	045-17862	N.PARACHUTE MF 18A-4 N04 69	PR	<input checked="" type="checkbox"/>
300235	WELL	PR	12/30/2009	GW	045-17861	N.PARACHUTE MF10C- 4 M04 696	PR	<input checked="" type="checkbox"/>
300236	WELL	PR	12/30/2009	GW	045-17860	N. PARACHUTE MF11A-4 N04 696	PR	<input checked="" type="checkbox"/>
300237	WELL	PR	02/10/2011	GW	045-17859	N.PARACHUTE MF06D- 4 N04 696	PR	<input checked="" type="checkbox"/>
301809	WELL	PR	12/30/2009	GW	045-18279	N. PARACHUTE MF15B-4 N04 696	PR	<input checked="" type="checkbox"/>
301810	WELL	PR	12/30/2009	GW	045-18280	N. PARACHUTE MF07B-4 N04 696	PR	<input checked="" type="checkbox"/>

**Equipment:**

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

<u>Signs/Marker:</u>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	SATISFACTORY	Capacity label is fading.		
CONTAINERS	SATISFACTORY			
BATTERY	SATISFACTORY			
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY Corrective Date: \_\_\_\_\_

Comment: 970-285-2615

Corrective Action: \_\_\_\_\_

<u>Spills:</u>				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Equipment:</b>					
Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Gas Meter Run	8	SATISFACTORY			
Ancillary equipment	2	SATISFACTORY	Chemical containers		
Plunger Lift	19	SATISFACTORY			
Gas Meter Run	19	SATISFACTORY	Gas lift		
Gas Meter Run	20	SATISFACTORY			

**Facilities:**  New Tank Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	<100 BBLs	STEEL AST	,

S/A/V: SATISFACTORY Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

**Paint**

Condition	Adequate
-----------	----------

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action \_\_\_\_\_ Corrective Date \_\_\_\_\_

Comment \_\_\_\_\_

**Venting:**

Yes/No	Comment
NO	

<b>Flaring:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 335598

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/AV:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**S/AV:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**S/AV:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Facility**

Facility ID: 284957 Type: WELL API Number: 045-12325 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Facility ID: 284958 Type: WELL API Number: 045-12324 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Facility ID: 284959 Type: WELL API Number: 045-12323 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Facility ID: 284960	Type: WELL	API Number: 045-12322	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Facility ID: 284961	Type: WELL	API Number: 045-12321	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Facility ID: 284962	Type: WELL	API Number: 045-12320	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Facility ID: 284963	Type: WELL	API Number: 045-12319	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Facility ID: 284964	Type: WELL	API Number: 045-12318	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Facility ID: 284965	Type: WELL	API Number: 045-12317	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Facility ID: 284966	Type: WELL	API Number: 045-12316	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Facility ID: 284967	Type: WELL	API Number: 045-12315	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Facility ID: 284968	Type: WELL	API Number: 045-12314	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Facility ID: 300233	Type: WELL	API Number: 045-17863	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Facility ID: 300234	Type: WELL	API Number: 045-17862	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Facility ID: 300235	Type: WELL	API Number: 045-17861	Status: PR	Insp. Status: PR

**Producing Well**

Comment: **Producing well**

Facility ID: 300236 Type: WELL API Number: 045-17860 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Producing well**

Facility ID: 300237 Type: WELL API Number: 045-17859 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Producing well**

Facility ID: 301809 Type: WELL API Number: 045-18279 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Producing well**

Facility ID: 301810 Type: WELL API Number: 045-18280 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Producing well**

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
Comment: \_\_\_\_\_  
Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
		Seeding				
Seeding						
Compaction	Pass					
				MHSP	Pass	
Gravel	Pass					
		Check Dams	Pass			
Berms	Pass					
Ditches	Pass					
		Gravel	Pass			
		Ditches	Pass			

S/A/V: SATISFACTOR  
 Y  
 Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674701782	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3672727">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3672727</a>