



Photo#1: View NE from entry to location



Photo#2: View of Location from top of East cut slope, looking to Center



Photo#3: View from Well head, looking NE.





Photo#4: More detail of Storage area.



Photo#5: Unused Tank on location. Action required removal in February 2015.