



Photo 1. View of sediment filled silt trap and wattle at culvert near well pad entrance. This area needs stabilization and maintenance.



Photo 2. View of weedy and sparse vegetation within western portion of project area. Field bindweed (*Convolvulus arvensis*) and cutleaf nightshade (*Solanum triflorum*) are weeds that are established on the slope.



Photo 3. View from southwestern corner of well pad facing center. Smooth brome (*Bromus inermis*) and western wheatgrass (*Pascopyrum smithii*) are becoming established here.