

**FORM
INSP**Rev
05/11

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


DE	ET	OE	ES
----	----	----	----

Inspection Date:

08/31/2015

Document Number:

674701787

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	<input type="checkbox"/>
	335256	335256	LONGWORTH, MIKE	2A Doc Num:	

Operator Information:OGCC Operator Number: 96850Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLCAddress: 1001 17TH STREET - SUITE #1200City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Inspection, WPX	970-263-2716	COGCCInspectionReports@wpxenergy.com	WPX Inspection Mail Box

Compliance Summary:QtrQtr: NESW Sec: 21 Twp: 6S Range: 95W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
06/08/2015	674701509			SATISFACTORY			No
12/16/2013	663902506			SATISFACTORY			No
12/16/2013	663902508			SATISFACTORY			No

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
111457	PIT		09/23/1999		-	2-W-21		<input type="checkbox"/>
211012	WELL	PR	01/11/1992	GW	045-06770	DOE 2-W-21	PR	<input type="checkbox"/>
276863	WELL	PR	09/20/2010	GW	045-10540	FEDERAL PA 23-21	PR	<input type="checkbox"/>
276864	WELL	AL	11/06/2008	LO	045-10541	FEDERAL PA 22-21	AL	<input checked="" type="checkbox"/>
276971	WELL	PR	09/20/2010	GW	045-10569	FEDERAL PA 33-21	PR	<input type="checkbox"/>
276972	WELL	PR	10/11/2010	GW	045-10568	FEDERAL PA 32-21	PR	<input type="checkbox"/>
300839	WELL	PR	02/16/2011	GW	045-18038	FEDERAL PA 412-21	PR	<input type="checkbox"/>
300840	WELL	PR	02/16/2011	GW	045-18039	FEDERAL PA 313-21	PR	<input type="checkbox"/>
300841	WELL	PR	02/16/2011	GW	045-18040	FEDERAL PA 413-21	PR	<input type="checkbox"/>

Inspector Name: LONGWORTH, MIKE

300842	WELL	PR	02/16/2011	GW	045-18041	FEDERAL PA 513-21	PR	
300843	WELL	PR	02/16/2011	GW	045-18042	FEDERAL PA 323-21	PR	
300844	WELL	PR	02/16/2011	GW	045-18043	FEDERAL PA 423-21	PR	
300845	WELL	PR	02/16/2011	GW	045-18044	FEDERAL PA 523-21	PR	
300846	WELL	PR	02/16/2011	GW	045-18045	FEDERAL PA 332-21	PR	
300847	WELL	PR	02/16/2011	GW	045-18046	FEDERAL PA 333-21	PR	
300848	WELL	PR	02/16/2011	GW	045-18047	FEDERAL PA 433-21	PR	
300849	WELL	PR	02/16/2011	GW	045-18048	FEDERAL PA 533-21	PR	
300850	WELL	PR	02/16/2011	GW	045-18049	FEDERAL PA 44-21	PR	
300851	WELL	PR	02/16/2011	GW	045-18050	FEDERAL PA 34-21	PR	
300852	WELL	PR	02/16/2011	GW	045-18051	FEDERAL PA 334-21	PR	
300853	WELL	PR	01/01/2012	GW	045-18052	FEDERAL PA 543-21	PR	
300854	WELL	PR	07/31/2010	GW	045-18053	FEDERAL PA 443-21	PR	
300855	WELL	PR	02/16/2011	GW	045-18054	FEDERAL PA 343-21	PR	
442570	SPILL OR RELEASE	CL	07/19/2015		-	SPILL/RELEASE POINT	CL	

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/A/V): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Venting:**

Yes/No	Comment

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 335256

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:Name: _____ Address: _____
Phone Number: _____ Cell Phone: _____Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 276864 Type: WELL API Number: 045-10541 Status: AL Insp. Status: AL

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Inspector Name: LONGWORTH, MIKE

Reportable: _____	GPS: Lat _____	Long _____
Proximity to Surface Water: _____	Depth to Ground Water: _____	
Water Well:		
DWR Receipt Num: _____	Owner Name: _____	GPS : _____
Field Parameters:		
Sample Location: _____		
Emission Control Burner (ECB): _____		
Comment: _____		
Pilot: _____	Wildlife Protection Devices (fired vessels): _____	
Reclamation - Storm Water - Pit		
Interim Reclamation:		
Date Interim Reclamation Started: _____		Date Interim Reclamation Completed: _____
Land Use: _____		
Comment: _____		
1003a.	Debris removed? _____ CM _____	
	CA _____	CA Date _____
	Waste Material Onsite? _____ CM _____	
	CA _____	CA Date _____
	Unused or unneeded equipment onsite? _____ CM _____	
	CA _____	CA Date _____
	Pit, cellars, rat holes and other bores closed? _____ CM _____	
	CA _____	CA Date _____
	Guy line anchors removed? _____ CM _____	
	CA _____	CA Date _____
	Guy line anchors marked? _____ CM _____	
	CA _____	CA Date _____
1003b.	Area no longer in use? _____	Production areas stabilized ? _____
1003c.	Compacted areas have been cross ripped? _____	
1003d.	Drilling pit closed? _____	Subsidence over on drill pit? _____
	Cuttings management: _____	
1003e.	Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____	
	Production areas have been stabilized? _____	Segregated soils have been replaced? _____
RESTORATION AND REVEGETATION		
<u>Cropland</u>		
	Top soil replaced _____	Recontoured _____ Perennial forage re-established _____
<u>Non-Cropland</u>		
	Top soil replaced _____	Recontoured _____ 80% Revegetation _____

Inspector Name: LONGWORTH, MIKE

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads _____

Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

No evidence of AL well 05-045-10541 FEDERAL PA 22-21.

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Pass _____

Well Release on Active Location ☐

Multi-Well Location ☒

Storm Water:

Loc Erosion BMPs

BMP
Maintenance

Lease Road Erosion
BMPs

Lease BMP
Maintenance

Chemical BMPs

Chemical BMP
Maintenance

Comment

S/A/V: _____

Corrective Date: _____

Comment: _____

CA: _____

Pits:



NO SURFACE INDICATION OF PIT