

Surprise Unit 2-08H

Inspection# 673402373

Migration of fine sediment
off of location standing on
northeast corner of location
looking south.



Migration of fine sediment
off of location standing on
northeast corner looking
east.



Sediment migration into
cuttings pile.



One of several low spots
visible in cuttings berm.

