



Photo 1. View of western edge of project area from northwestern corner facing southward. Annual vegetation such as sunflower (*Helianthus annuus*) and an unidentifiable annual crop within project area (on left) and perennial pasture vegetation such as western wheatgrass (*Pascopyrum smithii*) outside of project area (on right).



Photo 2. Birdseye view of revegetation within the project area which is mainly comprised of an annual crop and sunflower.



Photo 3. View of the northern portion of the access road from the well pad entrance facing westward. Cobble BMPs and straw mulch appear to be functioning.