



Photo 1:. Beginning of Ttransect #1, Disturbed Area, facing East.



Photo 2: Ground view at the midpoint of Transect #1, Disturbed Area.



**Photo 3: Facing North at midpoint of Transect #1, Disturbed Area**



**Photo 4: Facing South at midpoint of Transect #1, Disturbed Area.**




Photo 5: End of Transect #1, Disturbed Area, facing West.




Photo 6: Beginning of Transect #2 , Reference Area, facing West.



**Photo 7: Ground view at the midpoint of the Transect #2, Disturbed Area.**



**Photo 8: Facing North at midpoint of Transect.#2, Distrbed Area.**



**Photo 9: Facing South at midpoint of Transect #2, Disturbed Area.**



**Photo 10: Facing East at end of Transect #2, Disturbed Area.**