

## Cover Data

Date: 8/25/15

Inspected By:

Lou Colby

Location/Operator:

KLT Gas loc# 399444

107-06218

Transect #/disturbed/Ref	#1 Disturbed 40.48885 SW -107.40588 NW SE End transect - Photo other Aspect/Slope	Totals
Cryptogams (eg. Moss, lichen)	Litter :: 14 Bare Soil : 10 Rock : 2 Total Weeds O Total Desirable Species 74 80% Check 74/71 = 104% PASS	
	1st Hit 2nd/P	1st Hit 2nd/P
w Grass X X	X X X X 60	X X X X X X 60
vetch	[ ] 7	:: 3
clover	[ ] 7	[ ] 8
dood Flax Delmat	O	: 4
	100	100

2nd = second hit, P = plant present but not hit

2nd= second hit; P= plant species present but not hit