



Photo #1: View of Location looking North. Vegetation within old well pad area is not continuous with undisturbed area.



Photo #2 : Vegetation in area of location on North side of fence (excluding Livestock) is more robust.





Photo #3: Location view looking SW.



Photo #4: Close up view of surface Conditions. Erosion and soil migration imminent if CAs not applied.





Photo # 5 : Grasses have established, but heavy use has restricted population expansion.