



Photo# 1: Beginning of Transect #1 , Disturbed Area, facing West.



Photo# 2: Ground view at midpoint of Transect #1,Disturbed.



Photo# 3: View North at midpoint of Transect #1, Disturbed.



Photo# 4: View South at midpoint of Transect #1, Disturbed.



Photo# 5: Facing East at end of Transect #1, Disturbed.



Photo# 6: Beginning of Transect #2, Reference area , facing West.



Photo# 7: Ground view at midpoint of Transect #2, Reference.



Photo# 8: Facing North at midpoint of Transect #2, Reference.



Photo# 9: Facing South at midpoint of Transect #2, Reference.



Photo# 10: Facing East at end of Transect #2, Reference.