



**photo 1:** Facing southwest towards the location.



**photo 2:** Fence around the pit appears to be fixed.



**photo 3:** Pit at the west side of the location.



**photo 4:** Bull thistle (list B noxious weed) was found growing at the northwest side of the location.



**photo 5:** The excavator bucket (unused equipment) has been removed since the previous inspection.



**photo 6:** Facing towards the southeast side of the location.



**photo 7:** Facing towards the southeast corner of the location.



**photo 8:** Southeast corner of the location facing northeast.