

**PHOTOGRAPHIC LOG
INTERIM RECLAMATION COMPLETION
CAERUS MESA FIELD**



PHOTO 1

Subject: Caerus Puckett 31B-7
Location: 39.4577°N 108.14719°W
Date: 08/25/2015
Direction of View: North



PHOTO 2

Subject: Caerus Puckett 31B-7
Location: 39.4577°N 108.14719°W
Date: 08/25/2015
Direction of View: East



PHOTO 3

Subject: Caerus Puckett 31B-7
Location: 39.4577°N 108.14719°W
Date: 08/25/2015
Direction of View: South

**PHOTOGRAPHIC LOG
INTERIM RECLAMATION COMPLETION
CAERUS MESA FIELD**



PHOTO 4

Subject: Caerus Puckett 31B-7
Location: 39.4577°N 108.14719°W
Date: 08/25/2015
Direction of View: West



PHOTO 5

Subject: Caerus Puckett 31B-7
Location: 39.4577°N 108.14719°W
Date: 08/25/2015
Direction of View: Pad Surface



PHOTO 6

Subject: Caerus Puckett 31B-7
Location: 39.4577°N 108.14719°W
Date: 08/25/2015
Direction of View: Reference Area, East side of pad outside of construction site boundary