

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:  
09/17/2015Document Number:  
674701832Overall Inspection:  
SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	335667	335667	LONGWORTH, MIKE	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, General	970-285-2665	cogcc.inspections@encana.com	EnCana Inspection email

**Compliance Summary:**QtrQtr: SENW Sec: 23 Twp: 5S Range: 96W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
02/04/2015	674700954			<b>ACTION REQUIRED</b>			No

**Inspector Comment:**Follow up to 02/04/2015 inspection doc # 674700954. Corrective actions have been made.**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
282296	WELL	PR	08/03/2006	GW	045-11726	N PARACHUTE WF06C-23 F23596	PR	<input checked="" type="checkbox"/>
291476	WELL	PR	01/31/2009	GW	045-14383	N PARACHUTE WF12D-23 F23596	PR	<input checked="" type="checkbox"/>
291501	WELL	PR	07/31/2008	GW	045-14427	N PARACHUTE WF14C-23 F23596	PR	<input checked="" type="checkbox"/>
291502	WELL	PR	07/23/2007	GW	045-14426	N PARACHUTE WF15A-23 F23596	PR	<input checked="" type="checkbox"/>
291503	WELL	PR	01/31/2009	GW	045-14425	N PARACHUTE WF05C-23 F23596	PR	<input checked="" type="checkbox"/>
291504	WELL	AL	05/27/2011	LO	045-14424	ENCANA RPW 511-23-596	AL	<input type="checkbox"/>
291505	WELL	PR	02/01/2012	GW	045-14423	N PARACHUTE WF11D-23 F23596	PR	<input checked="" type="checkbox"/>
291506	WELL	PR	07/08/2009	GW	045-14422	N PARACHUTE WF06D-23 F23596	PR	<input checked="" type="checkbox"/>
291508	WELL	PR	04/11/2012	GW	045-14421	N. PARACHUTE WF 14A-23F23596	PR	<input checked="" type="checkbox"/>
291510	WELL	AL	05/27/2011	LO	045-14420	ENCANA RPW 312-23-596	AL	<input type="checkbox"/>

Inspector Name: LONGWORTH, MIKE

291512	WELL	PR	03/01/2009	GW	045-14419	N PARACHUTE WF12A-23 F23596	PR	<input checked="" type="checkbox"/>
291514	WELL	PR	07/23/2007	GW	045-14418	N PARACHUTE WF14B-23 F23596	PR	<input checked="" type="checkbox"/>
291518	WELL	PR	04/01/2008	GW	045-14417	N PARACHUTE WF05D-23 F23596	PR	<input checked="" type="checkbox"/>
291523	WELL	AL	05/27/2011	LO	045-14416	ENCANA RPW 411-23-596	AL	<input type="checkbox"/>
291524	WELL	AL	05/27/2011	LO	045-14415	ENCANA RPW 311-23-596	AL	<input type="checkbox"/>
291525	WELL	PR	01/01/2009	GW	045-14414	N PARACHUTE WF11B-23 F23596	PR	<input checked="" type="checkbox"/>
291526	WELL	AL	05/27/2011	LO	045-14413	ENCANA RPW 12-23-596	AL	<input type="checkbox"/>
291527	WELL	PR	07/23/2007	GW	045-14412	N PARACHUTE WF11A-23 F23596	PR	<input checked="" type="checkbox"/>
291528	WELL	AL	05/27/2011	LO	045-14411	ENCANA RPW 11-23-596	AL	<input type="checkbox"/>
291529	WELL	PR	01/19/2009	GW	045-14410	N PARACHUTE WF12B-23 F23596	PR	<input checked="" type="checkbox"/>
291530	WELL	PR	04/01/2012	GW	045-14408	N PARACHUTE WF11C-23 F23596	PR	<input checked="" type="checkbox"/>
291531	WELL	AL	05/27/2011	LO	045-14409	ENCANA RPW 22-23-596	AL	<input type="checkbox"/>

**Equipment:**Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location****Signs/Marker:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	SATISFACTORY			
CONTAINERS	SATISFACTORY			
WELLHEAD	SATISFACTORY			
BATTERY	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: **800-791-7691**

Corrective Action: \_\_\_\_\_

**Spills:**

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

<b>Venting:</b>		
Yes/No	Comment	
NO		

<b>Flaring:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 335667

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/A/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 282296 Type: WELL API Number: 045-11726 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Inspector Name: LONGWORTH, MIKE

Facility ID:	291476	Type:	WELL	API Number:	045-14383	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	291501	Type:	WELL	API Number:	045-14427	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	291502	Type:	WELL	API Number:	045-14426	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	291503	Type:	WELL	API Number:	045-14425	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	291505	Type:	WELL	API Number:	045-14423	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	291506	Type:	WELL	API Number:	045-14422	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	291508	Type:	WELL	API Number:	045-14421	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	291512	Type:	WELL	API Number:	045-14419	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	291514	Type:	WELL	API Number:	045-14418	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	291518	Type:	WELL	API Number:	045-14417	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	291525	Type:	WELL	API Number:	045-14414	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	291527	Type:	WELL	API Number:	045-14412	Status:	PR	Insp. Status:	PR

**Producing Well**Comment: **Producing well**

Facility ID: 291529 Type: WELL API Number: 045-14410 Status: PR Insp. Status: PR

**Producing Well**Comment: **Producing well**

Facility ID: 291530 Type: WELL API Number: 045-14408 Status: PR Insp. Status: PR

**Producing Well**Comment: **Producing well****Environmental****Spills/Releases:**

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

**Water Well:**

Lat Long

DWR Receipt Num: Owner Name: GPS :

**Field Parameters:**

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Debris removed? Pass CM

CA CA Date

Waste Material Onsite? Pass CM

CA CA Date

Unused or unneeded equipment onsite? Pass CM

CA CA Date

Pit, cellars, rat holes and other bores closed? CM

CA CA Date

Guy line anchors removed? CM

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Inspector Name: LONGWORTH, MIKE

S/A/V: SATISFACTOR

Corrective Date: \_\_\_\_\_

Y

Comment: Cut slope has been reclaimed.

CA: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Follow up to 02/04/2015 inspection doc # 674700954. Corrective actions have been made.	longworm	09/17/2015