

Declar, Fassler 1
121-08439

9/19/2015

Complaint

Waste pile @ wellhead location
(debris (pipe pieces) in pile)



09.19.2015 10:03

Waste pile next to
previous slide

09.19.2015 10:03

Both waste/soil piles at wellhead
location looking NE



09.19.2015 10:05

Erosion rill between wellhead and pit

09.19.2015 10:06

Fenced pit location looking N
(~200'x200')



09.19.2015 10:04

Pit reclamation looking E



09.19.2015 10:06

Pit reclamation looking NW



09.19.2015 10:06

Pit cut

09.19.2015 10:09



Pit cut



09.19.2015 10:09

Reclamation cut outside of
fenced pit (2' cut-~320'x40')



09.19.2015 10:10

Reclaimed area N of fenced pit location
(looking S)



09.19.2015 10:12



Reclaimed
area N of
fenced pit
location

09.19.2015 10:15

Drainage NE of pit location
(240' from end of reclaimed
area N of fenced pit location



09.19.2015 10:13