

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
09/23/2015

Document Number:
674701855

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>324416</u>	<u>324416</u>	<u>LONGWORTH, MIKE</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>96850</u>
Name of Operator:	<u>WPX ENERGY ROCKY MOUNTAIN LLC</u>
Address:	<u>ONE WILLIAMS CENTER - FL 35</u>
City:	<u>TULSA</u> State: <u>OK</u> Zip: <u>74172</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Inspection, WPX	970-263-2716	COGCCInspectionReports@wpxenergy.com	WPX Inspection Mail Box

Compliance Summary:

QtrQtr: NWNW Sec: 17 Twp: 5S Range: 97W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/08/2015	674701235			SATISFACTORY			No
06/21/2013	663801170			SATISFACTORY	I		No

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
290850	WELL	PR	06/04/2007	GW	045-14224	CHEVRON TR22-17-597	PR	<input checked="" type="checkbox"/>
414580	PIT	AC	12/03/2009		-	CHEVRON TR 11-17-597 PAD	AC	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			
CONTAINERS	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			
BATTERY	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY Corrective Date: _____

Comment: 970-285-9377

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK BATTERY	SATISFACTORY			
SEPARATOR	SATISFACTORY			
WELLHEAD	SATISFACTORY			
PIT	SATISFACTORY			

Equipment:					
Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Dehydrator	1	SATISFACTORY			
Plunger Lift	1	SATISFACTORY			
Bird Protectors	3	SATISFACTORY			
Horizontal Heated Separator	2	SATISFACTORY			
Ancillary equipment	1	SATISFACTORY	Chemical container at well.		

Facilities: New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
METHANOL	1	<50 BBLS	STEEL AST	,

S/A/V: SATISFACTORY Comment: _____

Corrective Action: _____ Corrective Date: _____

Paint

Condition Adequate

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action					Corrective Date
Comment					

Facilities: New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS	
PRODUCED WATER	1	300 BBLS	STEEL AST	,	
S/AV: SATISFACTORY	Comment:				
Corrective Action:					Corrective Date:

Paint

Condition	Adequate
Other (Content)	_____
Other (Capacity)	_____
Other (Type)	_____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment				

Venting:

Yes/No	Comment
YES	Braden open to vent.

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 324416

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 290850 Type: WELL API Number: 045-14224 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 414580 Type: PIT API Number: - Status: AC Insp. Status: AC

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS: _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:
 Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
 Land Use: _____
 Comment: _____

1003a. Debris removed? _____ CM _____
 CA _____ CA Date _____
 Waste Material Onsite? _____ CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? _____ CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____
 1003 f. Weeds Noxious weeds? _____
 Comment: _____
 Overall Interim Reclamation

Final Reclamation/ Abandoned Location:
 Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____
 Final Land Use: _____
 Reminder: _____
 Comment: _____
 Well plugged _____ Pit mouse/rat holes, cellars backfilled _____
 Debris removed _____ No disturbance /Location never built _____
 Access Roads Regraded _____ Contoured _____ Culverts removed _____
 Gravel removed _____
 Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____
 Compaction alleviation _____ Dust and erosion control _____
 Non cropland: Revegetated 80% _____ Cropland: perennial forage _____
 Weeds present _____ Subsidence _____
 Comment: _____
 Corrective Action: _____ Date _____
 Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Check Dams	Pass			
				MHSP	Pass	
Compaction	Pass					
		Ditches	Pass			
		Gravel	Pass			
		Culverts	Pass			
Seeding	Pass					
Gravel	Pass					

S/A/V: SATISFACTOR Corrective Date: _____
 Y _____
 Comment: _____
 CA: _____

Pits: NO SURFACE INDICATION OF PIT

Inspector Name: LONGWORTH, MIKE

Pit Type: Produced Water Lined: YES Pit ID: 414580 Lat: 39.618640 Long: -108.308700

Lining:

Liner Type: Plastic Liner Condition: Adequate

Comment: _____

Fencing:

Fencing Type: Netting/Fen Fencing Condition: Adequate

Comment: _____

Netting:

Netting Type: Fence/Net Netting Condition: Good

Comment: _____

Anchor Trench Present: YES Oil Accumulation: NO 2+ feet Freeboard: _____

Pit (S/AV): SATISFACTOR Comment: _____

Corrective Action: _____ Date: _____

Permit:	Facility ID	Permit Num	Expiration Date
	414580	1631108	

Monitoring:	Monitoring Type	Comment
	Telemetry	