



Photo 1. View from southeastern corner of project area facing center.



Photo 2. View of eastern portion of project area from southeastern corner facing northward. Revegetation of grasses such as intermediate wheatgrass (*Thinopyrum intermedium*) is progressing.



Photo 3. View of western portion of project area from southwestern corner facing northward. Dense intermediate wheatgrass is growing here.



Photo 4. View of rill erosion and sparse revegetation in eastern portion of project area.