

**FORM
INSP**Rev
05/11

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

09/25/2015

Document Number:

674701876

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	335838	335838	LONGWORTH, MIKE	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 10516Name of Operator: LINN OPERATING INCAddress: 600 TRAVIS STREET #5100City: HOUSTON State: TX Zip: 77002

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Burns, Bryan		bburns@linnenergy.com	
Johnson, Derek	970-285-2200	dsjohnson@linnenergy.com	
Foster, Michael	281-840-4375	MFoster@linnenergy.com	Regulatory Compliance Specialist II
White, Brent		bwhite@linnenergy.com	Production Foreman

Compliance Summary:

QtrQtr:	<u>SWSE</u>	Sec:	<u>16</u>	Twp:	<u>5S</u>	Range:	<u>95W</u>
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
08/20/2014	674700219			SATISFACTORY			No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
287707	WELL	XX	11/25/2013	LO	045-13015	LONG RIDGE 15D O16 595	ND	<input checked="" type="checkbox"/>
287708	WELL	XX	11/25/2013	LO	045-13014	LONG RIDGE 16B O16 595	ND	<input checked="" type="checkbox"/>
287709	WELL	XX	11/25/2013	LO	045-13013	LONG RIDGE 16A O16 595	ND	<input checked="" type="checkbox"/>
287710	WELL	XX	11/25/2013	LO	045-13012	LONG RIDGE 15A O16 595	ND	<input checked="" type="checkbox"/>
287711	WELL	XX	11/25/2013	LO	045-13011	LONG RIDGE 16C O16 595	ND	<input checked="" type="checkbox"/>
287712	WELL	XX	11/25/2013	LO	045-13010	LONG RIDGE 14A O16 595	ND	<input checked="" type="checkbox"/>
287713	WELL	XX	11/25/2013	LO	045-13009	LONG RIDGE 02A O16 595	ND	<input checked="" type="checkbox"/>
287714	WELL	XX	11/25/2013	LO	045-13008	LONG RIDGE 15C O16 595	ND	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Inspector Name: LONGWORTH, MIKE

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>8</u>	Production Pits: _____
Condensate Tanks: <u>5</u>	Water Tanks: <u>1</u>	Separators: <u>1</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: <u>1</u>	Oil Pipeline: _____	Water Pipeline: <u>1</u>
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: <u>2</u>
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
DRILLING/RECOMP	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: 970-285-2200

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	<u>8 conductors</u>		

Venting:

Yes/No	Comment
NO	

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 335838

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Group	User	Comment	Date
OGLA	kubeczkod	Any pit constructed to hold fluids (reserve pit, production pit; except for flare pit) must be lined.	10/21/2010

OGLA	kubeczkod	Notice to Operators (NTO) Drilling Wells on the Roan Plateau in Garfield County: Comply with all provisions of the June 12, 2008 Notice to Operators (NTO) Drilling Wells Within ¾ Mile of the Rim of the Roan Plateau in Garfield County – Pit Design, Construction, and Monitoring Requirements. At a minimum, the following condition of approval (COA) will apply: All pits must be lined.	10/21/2010
OGLA	kubeczkod	Operator must ensure 110 percent secondary containment for any volume of fluids contained at well site during drilling and completion operations; including, but not limited to, construction of a berm or diversion dike, diversion/collection trenches within and/or outside of berms/dikes, site grading, or other comparable measures (i.e., BMPs associated with stormwater management) sufficiently protective of the nearby surface water. If fluids are conveyed via pipeline, operator must implement best management practices to contain any unintentional release of fluids.	10/21/2010
OGLA	kubeczkod	The nearby hillside must be monitored for any day-lighting of drilling fluids throughout the drilling of the surface casing interval.	10/21/2010
OGLA	kubeczkod	The access road will be constructed as to not allow any sediment to migrate from the access road to nearby surface water or any drainages leading to surface water.	10/21/2010
OGLA	kubeczkod	No portion of any pit that will be used to hold liquids shall be constructed on fill material, unless the pit and fill slope are designed and certified by a professional engineer, subject to review and approval by the director prior to construction of the pit. The construction and lining of the pit shall be supervised by a professional engineer or their agent. The entire base of the pit must be in cut.	10/21/2010
OGLA	kubeczkod	The location is in an area of high run off/run-on potential; therefore the pad shall be constructed to prevent any stormwater run-on and /or stormwater runoff.	10/21/2010
OGLA	kubeczkod	The moisture content of any drill cuttings in a cuttings pit, trench, or pile shall be as low as practicable to prevent accumulation of liquids greater than de minimis amounts. At the time of closure, the drill cuttings must also meet the applicable standards of table 910-1.	10/21/2010

S/A/V: SATISFACTORY

Comment:

8 conductors set on location.

CA:

Date:

Wildlife BMPs:

BMP Type	Comment
Drilling/Completion Operations	<p>The following list of Best Management Practices (BMP's) that will be implemented by Berry Petroleum Company during the pad construction, well drilling, well completion, natural gas production and reclamation phases of activity on the Long Ridge O16 595 well Pad.</p> <p>A total of 8 wells will be directionally drilled from the N15 well pad. Directional drilling has enabled Berry Petroleum Company to reduce the number of well pads required for gas recovery and will minimize surface damage.</p> <p>The O16 well pad will be constructed adjacent to an existing road. This eliminates the need to construct an additional road for access and avoids additional surface disturbance.</p> <p>In general, Berry Petroleum Company will comply with all applicable federal, state and local statutes, rules, regulations and ordinances, including those of OSHA, the COGCC and the CDPHE. Relating to safety and the environment.</p> <p>During construction of the well pad, topsoil will be isolated from other soils and placed and stacked per COGCC requirements. All cuts, fill slopes, pits and topsoil piles will be stabilized and revegetated immediately following construction.</p> <p>The pad will be constructed in compliance with CDPHE Stormwater Discharge regulations. The reserve/completion pit will be fenced/flagged and/or netted to prevent entry of wildlife (including birds) and livestock.</p> <p>Bear proof dumpsters/trash cans will be used on the location for solid/food waste disposal. Noxious weeds will be controlled.</p> <p>Temporary housing for the drill rig crews will meet all Garfield County regulations. The housing quarters will receive 24/7 supervision by Berry Petroleum Company.</p> <p>Production tanks shall be placed on a non-permeable liner and surrounded by a metal containment wall at least 3 feet in height.</p>

S/A/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

--

Summary of Operator Response to Landowner Issues:

--

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

--

Facility

Facility ID: 287707	Type: WELL	API Number: 045-13015	Status: XX	Insp. Status: ND
---------------------	------------	-----------------------	------------	------------------

Facility ID: 287708	Type: WELL	API Number: 045-13014	Status: XX	Insp. Status: ND
---------------------	------------	-----------------------	------------	------------------

Inspector Name: LONGWORTH, MIKE

Facility ID:	287709	Type:	WELL	API Number:	045-13013	Status:	XX	Insp. Status:	ND
Facility ID:	287710	Type:	WELL	API Number:	045-13012	Status:	XX	Insp. Status:	ND
Facility ID:	287711	Type:	WELL	API Number:	045-13011	Status:	XX	Insp. Status:	ND
Facility ID:	287712	Type:	WELL	API Number:	045-13010	Status:	XX	Insp. Status:	ND
Facility ID:	287713	Type:	WELL	API Number:	045-13009	Status:	XX	Insp. Status:	ND
Facility ID:	287714	Type:	WELL	API Number:	045-13008	Status:	XX	Insp. Status:	ND

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Inspector Name: LONGWORTH, MIKE

Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
1003c. Compacted areas have been cross ripped? _____
1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
Cuttings management: _____
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
Check Dams	Pass					
Ditches	Pass					

Inspector Name: LONGWORTH, MIKE

		Check Dams	Pass			
Seeding	Pass					
Compaction	Pass					
Berms	Pass					
		Ditches	Pass			
		Gravel	Pass			
Gravel	Pass					

S/A/V: SATISFACTOR
Y

Corrective Date: _____

Comment:

CA:

Pits: ☒ NO SURFACE INDICATION OF PIT