

PO 12-12

Inspection# 673402472

Tanks labeled as permanently out of use for over 12 months.



Erosion gully leaving location on north side.



Erosion gully leaving location on north side. Noxious weeds visible on sides of gully.



Erosion gully on north side of location. Hard hat for scale.



Noxious weeds on location perimeter.



Rills on access road.



Access road overgrown.
Sediment migration down
access road.

