



Photo 1. View of southwestern edge of project area from western portion facing southeastward. Rocks and soil make up an approximately 6-foot-tall fill slope.



Photo 2. View of approximately 110 foot wide by 110 foot long area on the well pad covered in woody debris. From southern edge of debris pile facing northward.





Photo 3. Another view of woody debris pile on well pad.



Photo 4. View of project area from eastern corner facing center. Native grasses such as purple three-awn (*Aristida purpurea*) and shrubs such as snakeweed (*Gutierrezia sarothrae*) are established along the cut-slope in this area. Revegetation on the well pad is largely comprised species such as rubber rabbitbrush (*Chrysothamnus nauseosus*) and Indian ricegrass (*Achnatherum hymenoides*).





Photo 5. View of western edge of working area dense woody debris and cheatgrass along edge.



Photo 6. View of access road from well pad entrance facing northward.





Photo 7. View of adjacent pinon/juniper habitat and National Monument setting of well pad from southwestern edge facing southwestward.