







It is observed that low point is approximately 8-10" above pad surface





It is observed that low point is approximately 8-10" above pad surface. Note; no labels on tanks.





Spill below hammer union





Discoloration of gravel on north side of tank battery.



Spill below hammer union





Liner day lighting on Westside of location