

Elk Springs Unit 4

Inspection# 673402516

No capacity on produced
water label.

9/30/2015

Inspection 673402516



Approximately 15 feet
setback between heated
separator and heated tank.
Jeep for scale of setback.

9/30/2015

Inspection 673402516



Approximately 15 feet
setback between heated
separator and heated
tank.

4/6/2015
Inspection 673401981

