

FORM
5Rev
10/14State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

400247729

Date Received:

05/14/2012

DRILLING COMPLETION REPORT

Per Rule 308A, this form and all required attachments shall be submitted after completing the drilling operations to drill, sidetrack, or deepen a wellbore and after changing the casing and/or cement configuration of a wellbore. If any attempt has been made to test, complete, or produce the well, the operator shall also submit a Form 5A (Completed Interval Report) per Rule 308B. If the well has been plugged, the operator shall also submit a Form 6 (Well Abandonment Report) per Rule 311.

Completion Type ☒ Final completion ☐ Preliminary completion

OGCC Operator Number: 68710 Contact Name: CLAYTON DOKE
 Name of Operator: PETERSON ENERGY OPERATING INC Phone: (970) 669-7411
 Address: 2154 W EISENHOWER BLVD Fax: (970) 669-4077
 City: LOVELAND State: CO Zip: 80537 Email: cdoke@petersonenergy.com

API Number 05-123-33999-00 County: WELD
 Well Name: 392 VENTURES Well Number: 21-22D
 Location: QtrQtr: SENW Section: 22 Township: 6N Range: 67W Meridian: 6
 Footage at surface: Distance: 1510 feet Direction: FNL Distance: 2314 feet Direction: FWL
 As Drilled Latitude: 40.475543 As Drilled Longitude: -104.880754

GPS Data:

Date of Measurement: 02/09/2012 PDOP Reading: 1.5 GPS Instrument Operator's Name: B. BIRCH

** If directional footage at Top of Prod. Zone Dist: 624 feet Direction: FNL Dist: 1901 feet Direction: FEL

Sec: 22 Twp: 6N Rng: 67W

** If directional footage at Bottom Hole Dist: 637 feet Direction: FNL Dist: 1878 feet Direction: FEL

Sec: 22 Twp: 6N Rng: 67W

Field Name: WATTENBERG Field Number: 90750

Federal, Indian or State Lease Number:

Spud Date: (when the 1st bit hit the dirt) 12/21/2011 Date TD: 12/26/2011 Date Casing Set or D&A: 12/27/2011

Rig Release Date: Per Rule 308A.b.

Well Classification:

☐ Dry ☒ Oil ☐ Gas/Coalbed ☐ Disposal ☐ Stratigraphic ☐ Enhanced Recovery ☐ Storage ☐ Observation

Total Depth MD 7510 TVD** 7395 Plug Back Total Depth MD 7485 TVD** 7370

Elevations GR 4784 KB 4800 Digital Copies of ALL Logs must be Attached per Rule 308A ☒

List Electric Logs Run:

Density, Neutron, Induction, CBL

CASING, LINER AND CEMENT

Casing Type	Size of Hole	Size of Casing	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Top	Cmt Bot	Status
SURF	12+1/4	8+5/8	24	0	458	260	0	458	VISU
1ST	7+7/8	4+1/2	11.6	0	7,501	815	1,465	7,501	CBL

STAGE/TOP OUT/REMEDIAL CEMENT

Cement work date: _____					
Method used	String	Cementing tool setting/perf depth	Cement volume	Cement top	Cement bottom

Details of work:

FORMATION LOG INTERVALS AND TEST ZONES

FORMATION NAME	Measured Depth		Check if applies		COMMENTS (All DST and Core Analysis must be submitted to COGCC)
	Top	Bottom	DST	Cored	
NIOBRARA	6,991		NO	NO	
CODELL	7,320		NO	NO	

Operator Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: CLAYTON DOKE

Title: PETROLEUM ENGINEER Date: 5/14/2012 Email: cdoke@petersonenergy.com

Attachment Check List

Att Doc Num	Document Name	attached ?			
<u>Attachment Checklist</u>					
400272620	CMT Summary *	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>
	Core Analysis	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>
	Directional Survey **	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>
	DST Analysis	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>
	Logs	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>
	Other	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>
<u>Other Attachments</u>					
400545592	DIRECTIONAL DATA	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>

General Comments

User Group	Comment	Comment Date
Permit	Attached new Data Sheet. Logs are uploaded into well file.	1/27/2014 9:04:43 AM
Permit	Requested new DS Data sheet. Form on hold.	11/11/2013 1:19:30 PM
Permit	Attached corrected DS and chaged BHL and TOP as per opr.	8/29/2012 2:30:38 PM
Permit	Received DS from Steve Freese via Peterson Eng., however it doesn't match the directional numbers on the form. Requested clarification from opr.	8/21/2012 10:02:55 AM
Permit	On Hold. Requested new directional survey.	7/31/2012 2:41:10 PM

Total: 5 comment(s)