

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

| DE | ET | OE | ES |
|----|----|----|----|
|----|----|----|----|

Inspection Date:
09/24/2015Document Number:
668003823Overall Inspection:
SATISFACTORY**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | 259320 | 307905 | DURAN, JOHN | <input type="checkbox"/> | |

Operator Information:OGCC Operator Number: 10369Name of Operator: NATURAL RESOURCE GROUP INCAddress: 1789 W LITTLETON BLVDCity: LITTLETON State: CO Zip: 80120

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|---------------------------|---------------------------------|-----------------|
| Bacon, Duane | 303-545-2620/303-579-6353 | energyoilandgas@gmail.com | All Inspections |
| Laired, Paul | 303-419-6005 | plaird@diversifiedresources.com | All Inspections |

Compliance Summary:QtrQtr: NWSW Sec: 4 Twp: 34S Range: 62W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 07/23/2015 | 668003586 | PR | SI | SATISFACTORY | | | No |
| 07/25/2014 | 668002364 | PR | PR | SATISFACTORY | P | | No |
| 07/11/2013 | 668001382 | PR | PR | SATISFACTORY | P | | No |
| 08/08/2012 | 668000514 | PR | PR | SATISFACTORY | | | No |
| 08/08/2011 | 200319949 | PR | PR | SATISFACTORY | | | No |
| 08/20/2010 | 200273592 | PR | PR | SATISFACTORY | | | No |
| 05/14/2009 | 200212470 | PR | PR | SATISFACTORY | | | No |
| 03/19/2009 | 200207225 | ES | PR | ACTION REQUIRED | | | Yes |
| 10/02/2008 | 200196878 | PR | SI | SATISFACTORY | | | No |
| 10/05/2005 | 200080761 | PR | SI | ACTION REQUIRED | | Fail | Yes |
| 07/08/2005 | 200075215 | PR | SI | ACTION REQUIRED | | Fail | Yes |
| 06/06/2005 | 200073963 | PR | SI | ACTION REQUIRED | | Fail | Yes |
| 03/30/2005 | 200068875 | PR | SI | ACTION REQUIRED | | Fail | Yes |
| 04/11/2003 | 200038088 | PR | SI | ACTION REQUIRED | | Fail | Yes |

Inspector Comment:**Related Facilities:**

Inspector Name: DURAN, JOHN

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|-------------------------------------|
| 259320 | WELL | PR | 06/08/2011 | GW | 071-07235 | GARCIA 4-12 | PR | <input checked="" type="checkbox"/> |

Equipment:Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location**Signs/Marker:**

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|----------|------------------------------|---------|-------------------|---------|
| WELLHEAD | SATISFACTORY | | | |

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?**Equipment:**

| Type | # | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|---------------------|---|------------------------------|------------------------|-------------------|---------|
| Ancillary equipment | 1 | SATISFACTORY | Wellhead and pipeline. | | |

Venting:

| Yes/No | Comment |
|--------|---------|
| | |

Flaring:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|------|------------------------------|---------|-------------------|---------|
| | | | | |

Predrill

Location ID: 259320

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 259320 Type: WELL API Number: 071-07235 Status: PR Insp. Status: PR

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

S/A/V: _____ CA Date: _____

CA: _____

Comment: Production Records : Feb. 2014

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Inspector Name: DURAN, JOHN

Comment: _____

Corrective Action: _____

Date: _____

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well:

Lat _____

Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____

Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____

Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____
CA _____ CA Date _____
Waste Material Onsite? _____ CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? _____ CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Inspector Name: DURAN, JOHN

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

S/A/V: SATISFACTOR
Y

Corrective Date: _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|--------------------------------|--------|------------|
| Production Records : Feb. 2014 | duranj | 10/12/2015 |