



J15 595 PAD | Facility ID 335568

DOCUMENT NO. 674701871—INSPECTION DATE 9/25/2015



BEFORE



AFTER

J15 595 PAD | Facility ID 335568

Document No. 674701871—Inspection Date 9/25/2015

Description: Repaired gate and fence at wells LR06D and LR06A on 10/13/2015



BEFORE



AFTER

J15 595 PAD | Facility ID 335568

Document No. 674701871—Inspection Date 9/25/2015

Description: Removed unused pit float balls on 10/13/2015



BEFORE



AFTER

J15 595 PAD | Facility ID 335568

Document No. 674701871—Inspection Date 9/25/2015

Description: Removed unused pit float balls on 10/13/2015



BEFORE



AFTER

J15 595 PAD | Facility ID 335568

Document No. 674701871—Inspection Date 9/25/2015

Description: Removed spilled chemical from spill pan on 10/13/2015