

Veneta 1-32D

Inspection# 673402536

No NFPA label on tanks.
Setback from pump and
separator housed in shed on
right not sufficient.



No NFPA diamonds on tanks.
Berm liner daylighting.



Equipment stored on location. Saturated absorbent pads.



Trash and debris.



Equipment stored on location.



Office building, fueling station and other misc equipment stored on location.

