

## Buffalo Ditch 1-32H

Inspection# 673402537

Tank labels sun faded. Berm low at far left loadout.



Chemical storage on location.



Close up of chemicals stored on location.



Close up of chemicals stored on location.





Close up of chemicals stored on location.



Close up of chemicals stored on location.



Close up of chemicals stored on location.



Close up of chemicals stored on location.





Equipment stored on location.



Debris and equipment on location.





Equipment and chemicals  
stored on location.



Equipment stored on  
location.



Equipment stored on  
location.

