

Carpenter 2-32

Inspection# 673402550

Noxious weeds inside berm.



Equipment stored on location.



Rough and rutted road.



Rough and rutted road.

