



Photo#1: Looking across pad area from SE corner of Location.



Photo#2: View along East Berm facing North

October 11, 2015

Location # 44064





Photo#3: View along West Berm facing North.



Photo#4: View along North Berm and Storm water drainage ditch facing East.





Photo#5. Disturbed area, not stabilized, adjacent to South end of pad area .



Photo#6: Operator Equipment at SW Corner of disturbed area.





Photo#7: Adjacent properties are either Native and Perennial Forage, or Mowed.



Photo#8: Adjacent properties are either Mowed or Native and Perennial Forage.





Photo#9: Knapweed, matured on Location.



Photo#10: Access Road Kochia.

October 11, 2015

Location # 44064