

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
10/08/2015
Document Number:
674300447
Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>261391</u>	<u>324172</u>	<u>Spencer, Stan</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>10163</u>
Name of Operator:	<u>NONSUCH NATURAL GAS INC</u>
Address:	<u>P O BOX 110066</u>
City:	<u>NAPLES</u> State: <u>FL</u> Zip: <u>34108</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Longworth, Mike		mike.longworth@state.co.us	
Lujan, Carlos		carlos.lujan@state.co.us	
Lee, David	239-289-9046	dlee@ngg.us.com	
Fischer, Alex		alex.fischer@state.co.us	

Compliance Summary:

QtrQtr: SWSW Sec: 14 Twp: 6S Range: 97W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
08/03/2015	674300376	PR	PR	ACTION REQUIRED			No
07/28/2010	1949073	PR	PR	ACTION REQUIRED			Yes
09/30/2009	200219094	CO	PR	ACTION REQUIRED			Yes
11/10/2008	200198277	PR	PR	ACTION REQUIRED	I		Yes
09/01/2008	200206563	PR	PR	SATISFACTORY			No
07/25/2008	200192842	PR	PR	ACTION REQUIRED	I		Yes
06/13/2007	200117612	ES	PR	ACTION REQUIRED			Yes
10/25/2005	200085049	ES	PR	ACTION REQUIRED	F	Fail	Yes
07/07/2005	200076105	PR	PR	ACTION REQUIRED		Fail	Yes
08/22/2002	200032793	PR	PR	SATISFACTORY		Pass	No
11/02/2001	200023544	DG	DG	SATISFACTORY		Pass	No

Inspector Comment:

Follow-up inspection to 8/3/13 at which time pit was out of service undergoing cleaning and repair. Nonsuch submitted and F-4 9/29/15 which stated "We have removed all fluids from the pit at this location. We hae steam cleaned and inspected the pit liner. We have concluded the liner is in good condition. We have repaired all holes in the mesh nettingand cover the pit with the mesh netting. We have returned the pit to service. We have removed all weeds from this locaiton." COGCC concurs. Inspection is satisfactory.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261391	WELL	PR	03/29/2006	GW	045-07948	CSOC 697-14 1	PR

Inspector Name: Spencer, Stan

279253	PIT	AC	08/10/2005	-	CSOC 697-14 1 PIT	AC
324172	LOCATION	AC	07/16/2010	-	CSOC 697-14-66S97W 14SWSW	AC
418328	PIT		07/16/2010	-	DANISH FLATS	

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/A/V): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 261391

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 0 Type: _____ API Number: - Status: _____ Insp. Status: _____

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: Follow-up inspection to 8/3/13 at which time pit was out of service undergoing cleaning and repair. Nonsuch submitted and F-4 9/29/15 whcih stated "We have removed all fluids from the pit at this location. We hae steam cleaned and inspected the pit liner. We have concluded the liner is in good condition. We have repaired all holes in the mesh nettingand cover the pit with the mesh netting. We have returned the pit to service. We have removed all weeds from this locaiton." Some gravel remains on liner edges and are pipes in contact with liner. Remove gravel. Discharge pipes should be on raised stands to prevent wear. Inspection is satisfactory.

Corrective Action: NA Date: _____

Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____
DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____
CA _____ CA Date _____

Waste Material Onsite? _____ CM _____
CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____
CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____
CA _____ CA Date _____

Guy line anchors removed? _____ CM _____
CA _____ CA Date _____

Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

Inspector Name: Spencer, Stan

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location

Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____

Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	418328	2607827	
	279253	400784191	
	279253	1433052	
	279253	400784191	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674300449	pit with cleaned liner	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3703693