

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

10/14/2015

Document Number:

675202138

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	334065	334065	CONKLIN, CURTIS	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Encana,		cogcc.inspections@encana.com	All Inspections

Compliance Summary:QtrQtr: NWSE Sec: 28 Twp: 7S Range: 95W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/26/2015	675201374			SATISFACTORY			No
07/16/2014	675100216			SATISFACTORY			No

Inspector Comment:Inspection to pass final reclamation on PA and DA wells only.**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
210228	WELL	PR	12/20/1996	GW	045-05187	FEDERAL 28-95	PR	<input type="checkbox"/>
279657	WELL	PA	10/07/2011	GW	045-11066	FEDERAL 28-9 (PJ28)	PA	<input checked="" type="checkbox"/>
279658	WELL	DA	12/24/2005	DA	045-11065	FEDERAL 28-15 (PJ28)	DA	<input checked="" type="checkbox"/>
279659	WELL	AL	04/09/2009	LO	045-11064	FEDERAL 28-16 (PJ28)	AL	<input type="checkbox"/>
279660	WELL	PA	10/08/2011	GW	045-11063	FEDERAL 28-7 (PJ28)	PA	<input checked="" type="checkbox"/>
283792	WELL	PR	09/13/2006	GW	045-11994	FEDERAL 28-15X (PJ28)	PR	<input type="checkbox"/>

Equipment:Location Inventory

Inspector Name: CONKLIN, CURTIS

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/A/V): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:

Yes/No	Comment
--------	---------

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
------	------------------------------	---------	-------------------	---------

Predrill

Location ID: 334065

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 279657 Type: WELL API Number: 045-11066 Status: PA Insp. Status: PA

Facility ID: 279658 Type: WELL API Number: 045-11065 Status: DA Insp. Status: DA

Facility ID: 279660 Type: WELL API Number: 045-11063 Status: PA Insp. Status: PA

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____		Date: _____	
Reportable: _____	GPS: Lat _____	Long _____	
Proximity to Surface Water: _____		Depth to Ground Water: _____	

Water Well:		Lat _____	Long _____
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	_____

Field Parameters:
Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit
--

Interim Reclamation:	
Date Interim Reclamation Started: _____	Date Interim Reclamation Completed: _____
Land Use: _____	
Comment: _____	

1003a.	Debris removed? _____	CM _____	CA _____	CA Date _____
	Waste Material Onsite? _____	CM _____	CA _____	CA Date _____
	Unused or unneeded equipment onsite? _____	CM _____	CA _____	CA Date _____
	Pit, cellars, rat holes and other bores closed? _____	CM _____	CA _____	CA Date _____
	Guy line anchors removed? _____	CM _____	CA _____	CA Date _____
	Guy line anchors marked? _____	CM _____	CA _____	CA Date _____

1003b. Area no longer in use? _____	Production areas stabilized ? _____
1003c. Compacted areas have been cross ripped? _____	
1003d. Drilling pit closed? _____	Subsidence over on drill pit? _____
Cuttings management: _____	
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____	
Production areas have been stabilized? _____	Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____	Recontoured _____	Perennial forage re-established _____
-------------------------	-------------------	---------------------------------------

Non-Cropland

Inspector Name: CONKLIN, CURTIS

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____ Pass _____

Well Release on Active Location ☐

Multi-Well Location ☒

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT