

## Focus Ranch Unit Federal 12-1

Inspection# 673402561

Rough road base beginning to develop ruts. Evidence of seeding on slope on right.



Rough road base in foreground on straight section of road. Base with topper in background transitioning back to base after completion of curve.





Transition from base to  
base with topper  
heading into curve in  
background.



Base with topper coming  
out of one curve in  
foreground, in center  
transition to only base, in  
background curve, base  
with topper.



Pre existing road for  
reference.

