

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

10/23/2015

Document Number:

674701964

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	335560	335560	LONGWORTH, MIKE	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, General	970-285-2665	cogcc.inspections@encana.com	EnCana Inspection email

Compliance Summary:QtrQtr: NWNW Sec: 9 Twp: 6S Range: 96W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
12/30/2014	674700797			SATISFACTORY			No
08/14/2014	674700197			SATISFACTORY			No
01/14/2014	663902648			SATISFACTORY	I		No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284554	WELL	PR	05/02/2006	GW	045-12211	N.PARACHUTE MF02C D09A 696	PR
284555	WELL	PR	09/01/2007	GW	045-12210	N.PARACHUTE MF02A D09A 696	PR
284556	WELL	PR	03/28/2007	GW	045-12209	N. PARACHUTE MF20C D09A696	PR
284557	WELL	PR	05/02/2006	GW	045-12208	N.PARCHUTE MF07C D09A 696	PR
284558	WELL	PR	01/27/2014	GW	045-12207	N.PARACHUTE MF07A D09A 696	PR
284559	WELL	PR	05/02/2006	GW	045-12206	N.PARACHUTE MF06C D09A 696	PR
284560	WELL	PR	11/10/2007	GW	045-12205	N.PARACHUTE MF 05B D09A 696	PR
289509	WELL	PR	02/28/2007	GW	045-13793	N. PARACHUTE MF20A D09A 696	PR
297094	WELL	PR	06/01/2009	GW	045-16299	N. PARACHUTE MF02B-9 D09A 69	PR

Inspector Name: LONGWORTH, MIKE

297095	WELL	PR	04/28/2009	GW	045-16300	N. PARACHUTE MF03C-9 D09A 69	PR	<input type="checkbox"/>
297096	WELL	PR	04/29/2009	GW	045-16301	N. PARACHUTE MF03A-9 D09A 69	PR	<input type="checkbox"/>
297097	WELL	PR	05/09/2009	GW	045-16302	N. PARACHUTE MF03D-9 D09A 69	PR	<input type="checkbox"/>
297098	WELL	DA	11/25/2008	GW	045-16303	N. PARACHUTE MF02C-9 D09A 69	DA	<input checked="" type="checkbox"/>
297099	WELL	PR	01/27/2014	GW	045-16304	N. PARACHUTE MF04D-9 D09A 69	PR	<input type="checkbox"/>
297100	WELL	PR	04/09/2009	GW	045-16305	N. PARACHUTE MF04A-9 D09A 69	PR	<input type="checkbox"/>
297101	WELL	PR	06/01/2009	GW	045-16306	N. PARACHUTE MF04C-9 D09A 69	PR	<input type="checkbox"/>
299810	WELL	PR	07/03/2009	GW	045-17757	N. PARACHUTE MF06B-9 D09A 69	PR	<input type="checkbox"/>
299811	WELL	PR	06/29/2009	GW	045-17758	N. PARACHUTE MF06C-9 D09A 69	PR	<input type="checkbox"/>
299812	WELL	PR	07/03/2009	GW	045-17759	N. PARACHUTE MF05D-9 D09A 69	PR	<input type="checkbox"/>
299813	WELL	PR	06/27/2009	GW	045-17760	N. PARACHUTE MF05B-9 D09A 69	PR	<input type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/A/V): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment

Flaring:

Type

Satisfactory/Action Required

Comment

Corrective Action

CA Date

Predrill

Location ID: 335560

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 297098 Type: WELL API Number: 045-16303 Status: DA Insp. Status: DA

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

	Lat	Long
DWR Receipt Num: _____	Owner Name: _____	GPS : _____
Field Parameters:		
Sample Location: _____		
Emission Control Burner (ECB): _____		
Comment: _____		
Pilot: _____	Wildlife Protection Devices (fired vessels): _____	

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

No evidence of MF02C-9 on location. Form 6 Well abandonment report doc. # 1927426

Corrective Action: _____

Date _____

Overall Final Reclamation _____ Pass _____

Well Release on Active Location ☒Multi-Well Location ☒**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT