

**PHOTOGRAPHIC LOG  
INTERIM RECLAMATION COMPLETION  
CAERUS PARACHUTE CREEK FIELD**



**PHOTO 1**

**Subject: Caerus Parachute Creek 7  
Location: 39.547222°N 108.120278°W  
Date: 08/25/2015  
Direction of View: North**



**PHOTO 2**

**Subject: Caerus Parachute Creek 7  
Location: 39.547222°N 108.120278°W  
Date: 08/25/2015  
Direction of View: East**



**PHOTO 3**

**Subject: Caerus Parachute Creek 7  
Location: 39.547222°N 108.120278°W  
Date: 08/25/2015  
Direction of View: South**



**PHOTOGRAPHIC LOG  
INTERIM RECLAMATION COMPLETION  
CAERUS PARACHUTE CREEK FIELD**



**PHOTO 4**

**Subject: Caerus Parachute Creek 7  
Location: 39.547222°N 108.120278°W  
Date: 08/25/2015  
Direction of View: West**



**PHOTO 5**

**Subject: Caerus Parachute Creek 7  
Location: 39.547222°N 108.120278°W  
Date: 08/25/2015  
Direction of View: Background**



**PHOTO 6**

**Subject: Caerus Parachute Creek 7  
Location: 39.547222°N 108.120278°W  
Date: 08/25/2015  
Direction of View: Pad Surface**