

**PHOTOGRAPHIC LOG
INTERIM RECLAMATION COMPLETION
CAERUS PARACHUTE CREEK FIELD**



PHOTO 1

**Subject: Caerus Parachute Creek 9
Location: 39.556049°N 108.117661°W
Date: 08/25/2015
Direction of View: North**



PHOTO 2

**Subject: Caerus Parachute Creek 9
Location: 39.556049°N 108.117661°W
Date: 08/25/2015
Direction of View: East**



PHOTO 3

**Subject: Caerus Parachute Creek 9
Location: 39.556049°N 108.117661°W
Date: 08/25/2015
Direction of View: South**

**PHOTOGRAPHIC LOG
INTERIM RECLAMATION COMPLETION
CAERUS PARACHUTE CREEK FIELD**



PHOTO 4

**Subject: Caerus Parachute Creek 9
Location: 39.556049°N 108.117661°W
Date: 08/25/2015
Direction of View: West**



PHOTO 5

**Subject: Caerus Parachute Creek 9
Location: 39.556049°N 108.117661°W
Date: 08/25/2015
Direction of View: Background**



PHOTO 6

**Subject: Caerus Parachute Creek 9
Location: 39.556049°N 108.117661°W
Date: 08/25/2015
Direction of View: Pad Surface**