



Photo 1. Photo taken from agricultural field, facing South towards well. Weeds and vegetative debris must be removed.



Photo 2. Photo taken from agricultural field, facing North. Crops have re-established, area contoured, but weeds and vegetative debris must be removed.



Photo 3. Photo taken from agricultural field, facing West. Crops have re-established, area contoured, but weeds and vegetative debris must be removed.



Photo 4. Photo taken from agricultural field, facing East. Crops have re-established, area contoured, but weeds and vegetative debris must be removed.



Photo 5. Reference photo taken from agricultural field, facing South.



Photo 6. Reference photo taken from agricultural field, facing North.



Photo 7. Reference photo taken from agricultural field, facing West.



Photo 8. Reference photo taken from agricultural field, facing East.