



Photo 1. View of eastern portion of project area from well pad entrance (northeast) facing southward. Revegetation is largely comprised native species such as rubber rabbitbrush (*Chrysothamnus nauseosus*), western wheatgrass (*Pascopyrum smithii*), and fourwing saltbush (*Atriplex canescens*).



Photo 2. View of stormwater BMP (cobble lining and silt trap) within northeastern portion of the project area.





Photo 3. View of erosional channel (approximately 1.5 feet wide and 8 inches deep) forming downstream of stormwater BMP in northeastern portion of the project area.





Photo 4. View of southern portion of the project area from the southeastern portion of the project area facing westward.





Photo 5. View of soil stockpile within the southwestern portion of the project area facing southward.





Photo 6. View of western portion of project area from southern edge facing northwestward.



Photo 7. View of access road from well pad entrance facing eastward.