

PetroHunter – 10200

Lake # 16-21

API 05-103-10973

by Lou Colby & Kyle Granahan

10/22/2015



Battery sign @ entrance



Trailer on location



Debris



Unused equipment






Pit liner – debris



Debris













Anchor not marked





Gauge on wellhead



Fluid in cellar