



photo 1: Well sign, Klingon 41-32



photo 2: Center of the location facing northwest towards wellhead.



photo 3: South side of the location facing northwest.



photo 4: Erosion is occurring along the north side of the location.



photo 5: Facing towards the northeast corner of the location.