

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:  
11/02/2015Document Number:  
674102725Overall Inspection:  
SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	433854	433854	Rickard, Jeff	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc.djinspections@encana.com	Group email
Adamczyk, Megan		megan.adamczyk@state.co.us	

**Compliance Summary:**QtrQtr: SWNW Sec: 5 Twp: 2N Range: 67W**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
433849	WELL	PR	12/02/2014	OW	123-37815	Vogl-McCoy 2B-5H-E267	PR	<input checked="" type="checkbox"/>
433850	WELL	PR	12/02/2014	OW	123-37816	VOGL-GEIST 2B-5H-E267	PR	<input checked="" type="checkbox"/>
433851	WELL	PR	01/09/2015	OW	123-37817	VOGL-GEIST 2A-5H-E267	PR	<input checked="" type="checkbox"/>
433852	WELL	PR	12/02/2014	OW	123-37818	VOGL-MCCOY 2C-5H-E267	PR	<input checked="" type="checkbox"/>
433853	WELL	PR	12/02/2014	OW	123-37819	Vogl-McCoy 2A-5H-E267	PR	<input checked="" type="checkbox"/>
433855	WELL	PR	12/02/2014	OW	123-37820	VOGL-MCCOY 2D-5H-E267	PR	<input checked="" type="checkbox"/>
433937	WELL	PR	12/02/2014	OW	123-37860	VOGL-GEIST 2C-5H-E267	PR	<input checked="" type="checkbox"/>
442867	TANK BATTERY	AC	01/09/2015		-	Vogl-Geist-McCoy 5H-E267	AC	<input type="checkbox"/>
442868	TANK BATTERY	AC	01/09/2015		-	Vogl-Geist-McCoy 5H-E267	AC	<input type="checkbox"/>

**Equipment:****Location Inventory**

Inspector Name: Rickard, Jeff

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>7</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>8</u>	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: <u>7</u>
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: <u>13</u>	Oil Tanks: <u>18</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

Emergency Contact Number (S/A/V): \_\_\_\_\_

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Spills:**

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

**Venting:**

Yes/No	Comment
--------	---------

**Flaring:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
------	------------------------------	---------	-------------------	---------

**Predrill**

Location ID: 433854

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/A/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

Group	User	Comment	Date
OGLA	youngr	The tank battery shall be constructed using a liner.	07/15/2013

**S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 433849 Type: WELL API Number: 123-37815 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

**Complaint**

Comment: Complaint DOC#200437869. Area resident filed a complaint about noise coming from location. Complainant stated the noise happened at random times and for random intervals. OGCC staff was on location on 11/2/15 and ran a sound survey. A scale was observed to be 37-40 db when no traffic was on CR15, OGCC staff talked to complainant and stated that the location was in compliance. OGCC staff informed the complainant that they could call inspector directly when the noise was happening next time it happened and OGCC staff will try to get to the location to measure the sound. 18A DOC#200437879.

**BradenHead**

Comment: Braden head is exposed at surface.

CA:

CA Date:

Facility ID: 433850 Type: WELL API Number: 123-37816 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

**BradenHead**

Comment: Braden head is exposed at surface.

CA:

CA Date:

Facility ID: 433851 Type: WELL API Number: 123-37817 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

**BradenHead**

Comment: Braden head is exposed at surface.

CA:

CA Date:

Facility ID: 433852 Type: WELL API Number: 123-37818 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

**BradenHead**

Comment: Braden head is exposed at surface.

CA:

CA Date:

Facility ID: 433853 Type: WELL API Number: 123-37819 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

**BradenHead**

Comment: Braden head is exposed at surface.

CA:

CA Date:

Facility ID: 433855 Type: WELL API Number: 123-37820 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

**BradenHead**

Comment: Braden head is exposed at surface.

CA:

CA Date:

Facility ID: 433937 Type: WELL API Number: 123-37860 Status: PR Insp. Status: PR

**Producing Well**Comment: **PR****BradenHead**Comment: **Braden head is exposed at surface.**

CA: \_\_\_\_\_

CA Date: \_\_\_\_\_

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

**Complaint:**

Tracking Num	Category	Assigned To	Description	Incident Date
200415687	NOISE	Gomez, Jason	On 10-23-2014 I was contacted by email from complaint Mike Lozinski who resides at 11755 county road 15, Longmont Co. 80504. The complaint stated in his email that the noise coming from the location across the road from his residence was causing him to be a woken in the night from the noise coming from the site. In a later email sent on 10-23-2014 the complaint indicated the noise was "squelching noise every 5-10 seconds that lasted about 2-3 seconds."	10/27/2014
200409898	NOISE	Gomez, Jason	On 7-28-2014 I was notified of a complaint recived by the COGCC office in reference to a noise complaint coming from a location to the southeast of the complaints residence of 11755 county road 15, Longmont Co. 80504. The complaint Michael A. Lozinski indicated the noise coming from the location was causing his home to shake, he also indicated the noise was continous 24/7 which was affecting his ability to sleep at night.	07/28/2014

Emission Control Burner (ECB): **Y** \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: **ON** \_\_\_\_\_ Wildlife Protection Devices (fired vessels): **YES** \_\_\_\_\_**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: **IRRIGATED**

Comment: \_\_\_\_\_

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors removed? Pass CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? In Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

#### RESTORATION AND REVEGETATION

##### Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

##### Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

#### **Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: IRRIGATED

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Inspector Name: Rickard, Jeff

Corrective Action:  Date

Overall Final Reclamation

Well Release on Active Location ☐

Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

S/A/V: SATISFACTOR Y Corrective Date:

Comment:

CA:

Pits: ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674102726	Sound Survey	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3714563">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3714563</a>