

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:
11/03/2015

Document Number:
680400303

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

| | | | | | |
|---------------------|---------------|---------------|------------------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | <u>288560</u> | <u>316873</u> | <u>BROWNING, CHUCK</u> | <input type="checkbox"/> | |

Operator Information:

OGCC Operator Number: 10453

Name of Operator: CCI PARADOX UPSTREAM LLC

Address: 811 MAIN STREET #3500

City: HOUSTON State: TX Zip: 77002

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------------|----------------|----------------------------|-----------------|
| Schaffner, Chrissy | (303) 906-1257 | chrissy.schaffner@cci.com | |
| Browning, Chuck | 970-433-4139 | chuck.browning@state.co.us | Field Inspector |

Compliance Summary:

QtrQtr: NWNW Sec: 30 Twp: 45N Range: 14W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 10/23/2012 | 668400761 | PR | PR | SATISFACTORY | I | | No |
| 05/18/2009 | 200211491 | PR | PR | SATISFACTORY | | | No |

Inspector Comment:

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|--|
| 288560 | WELL | PR | 04/20/2015 | GW | 113-06229 | HC BRAY 30-11-45-14 | PR <input checked="" type="checkbox"/> |

Equipment:

Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Lease Road:

| Type | Satisfactory/Action Required | comment | Corrective Action | Date |
|--------|------------------------------|---------|-------------------|------|
| Access | SATISFACTORY | | | |

| | | | | |
|------|--------------|--|--|--|
| Main | SATISFACTORY | | | |
|------|--------------|--|--|--|

| Signs/Marker: | | | | |
|----------------------|------------------------------|---------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| TANK LABELS/PLACARDS | SATISFACTORY | | | |
| WELLHEAD | SATISFACTORY | | | |

Emergency Contact Number (S/A/V): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

| Spills: | | | | |
|--|------|--------|-------------------|---------|
| Type | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

| Fencing/: | | | | |
|------------------|------------------------------|---------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| WELLHEAD | SATISFACTORY | | | |

| Equipment: | | | | | |
|-----------------------------|---|------------------------------|---------|-------------------|---------|
| Type | # | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| Gas Meter Run | 1 | SATISFACTORY | | | |
| Horizontal Heated Separator | 1 | SATISFACTORY | | | |
| Deadman # & Marked | 4 | SATISFACTORY | | | |

Facilities: New Tank Tank ID: _____

| Contents | # | Capacity | Type | SE GPS |
|----------------|---|----------|-----------|-----------------------|
| PRODUCED WATER | 1 | 400 BBLS | STEEL AST | 38.129231,-108.461609 |

S/A/V: SATISFACTORY Comment: _____

Corrective Action: _____ Corrective Date: _____

Paint

| | |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |

Corrective Action _____ Corrective Date _____

Comment _____

| Venting: | |
|-----------------|---------|
| Yes/No | Comment |
| NO | |

| Flaring: | | | | |
|-----------------|------------------------------|---------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| | | | | |

Predrill

Location ID: 288560

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/A/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/A/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 288560 Type: WELL API Number: 113-06229 Status: PR Insp. Status: PR

Producing Well

Comment: Gas Lift

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS: _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? Pass CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized? Pass

1003c. Compacted areas have been cross ripped? Pass

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? Pass Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ P _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms | Pass | Gravel | Pass | MHSP | Pass | |

S/A/V: SATISFACTOR _____ Corrective Date: _____
 Y _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT